



USTRAC

Facility Summary

Owner Name and Address: Shade Tree Enterprises, Inc. 105 E. Main St., P.O. Box 83 Glenwood WA 98619

Facility ID	Location Name	Location Street Address	Location City State	Zip	County	Tribe	SOC	C&E Status	LUST
4260138	Shade Tree Inn	105 E. Main St.	Glenwood, WA 98619	98619	Klickitat	Yakama	In SOC	No Visits	NA

Financial Responsibility

Type	Issuer	Policy Number	Effective Date Start	Effective Date End
------	--------	---------------	-------------------------	-----------------------

Contacts

Contact Name: Address: City State Zip: Phone: Fax: Email:

Tank Summary

M* = Manifold; C*=Compartment

Tank ID	Status	M* C* Installed	Closed	Product	Capacity	Tank Material / Sec. Mat.	Piping Material / Sec. Mat. / Type	Over / Spill / CP
1	Permanently Out of Us	No No 1/1/1971	10/23/1990	Gasoline	3000	Asphalt Coated or Bare Steel	Galvanized Steel	Not Listed No No No
2	Permanently Out of Us	No No 1/1/1971	11/30/1988	Gasoline	3000	Asphalt Coated or Bare Steel	Galvanized Steel	Not Listed No No No
3	Permanently Out of Us	No No 1/1/1966	11/30/1988	Diesel	500	Asphalt Coated or Bare Steel	Galvanized Steel	Not Listed No No No

Facility Actions

Inspection Date	Inspector	Action	SOC	C & E Status	SOC UST Status	Last Due Date	Closed Date	Number of Violations	Outstanding Violations
--------------------	-----------	--------	-----	--------------	-------------------	------------------	-------------	-------------------------	---------------------------

Lust Events



USTRAC Facility Summary

Event Date LUST Status Manager Last Milestone Last Closed Date

Facility General Comments

Source	Date	Comments
CBoulind	10/30/12	4260138: Formerly WA7115, Ecology transferred the file to EPA on 12/11/02 because Ecology said that it was on the Yakama reservation.



USTRAC

Profile: Owner

Owner: **Shade Tree Enterprises, Inc.**

Owner ID: 550

Street: 105 E. Main St., P.O. Box 83

Taxpayer ID:

City, State Zip: Glenwood WA 98619

Owner Type: Commercial

County: Klickitat

Email:

Phone: (509) 364-3471

Fax:

Facilities:

Facility ID: 4260138

Tribe: Yakama

Facility: Shade Tree Inn

Indian Land Status:

Address: 105 E. Main St.

Last Inspection: Not Visited

City, ST Zip: Glenwood WA 98619

Facility Type: Gas Station

C&E Status: No Visits

County: Klickitat

Facility Status: Operating

Last SOC: In SOC

AST: ☒

Operator:

Latitude: +46 ° 1 ' 06.18 "

SOC UST Status: NA

UIC: ☐

Phone: (509) 364-3471

Longitude: 121 ° 17 ' 34.27 "

LUST Status: NA

Marketer: ☐

Fax:

No. of Tanks: Active 0

Total 3

Contacts:

Contact Jerry Lorenz

Phone: (509) 364-3471

Address: P.O. Box 83

Fax:

Cell:

City, State: Glenwood

, WA

Zip: 98619

E-mail:

- | | |
|---|--|
| <input checked="" type="radio"/> Current | <input type="radio"/> Archive |
| <input checked="" type="checkbox"/> Owner | <input type="checkbox"/> Outreach <input type="checkbox"/> RP |
| <input type="checkbox"/> Operator | <input type="checkbox"/> CA Contact <input type="checkbox"/> Loc |
| <input type="checkbox"/> Manager | <input type="checkbox"/> Fee Contact |
| <input type="checkbox"/> Other | |

Comments:



Facility Tank Information

Facility: **Shade Tree Inn** Facility ID No: **4260138**
Street: **105 E. Main St.** Facility Description: **Gas Station**
City ST Zip: **Glenwood, WA 98619** Operator:
County: **Klickitat** Tribe: **Yakama**
Phone: **(509) 364-3471** LUST Status: **NA**
Latitude: **+46° 01' 18"** Longitude: **121° 17' 27"** Last Inspection Date: **Not Visited**
Owner: **Shade Tree Enterprises, Inc.** C&E Status: **No Visits**
Address: **105 E. Main St., P.O. Box 83** SOC Status: **In SOC**
Glenwood WA 98619 SOC UST Status: **NA**

Tank Status Tank ID: **0001**
Alt Tank ID:
Compartment: ☐ Manifolder: ☐
Tank Status: **Permanently Out of Use**
Installation Date (Mo/Yr): **1/1/1971**
Est. Total Capacity (gallons): **3000**
Federally Regulated Tank: ☒

Tank Construction Material
Tank Material: **Asphalt Coated or Bare Steel**
Secondary Material:
Tank Manufacturer:
Tank Repaired: ☐ Used for Emergency Power Generation: ☐

Piping Construction Material
Piping Material: **Galvanized Steel**
Secondary Material:
Piping Manufacturer:
Type of Pipe: **Not Listed**
Piping Repaired: ☐ Metal in Contact with Ground: ☐

Corrosion Protection
☐ Yes ☒ No ☐ NA
FRP/ Flex Pipe: ☐
Impressed Current: ☐
Sacrificial Anodes: ☐
Interior Lining: ☐
Latest Upgrade Install Date:

Spill / Overfill Protection
Spill Protected: ☐ Exempt: ☐
Overfill Protected: ☐
(Check all that apply.) Ball Float: ☐ (Tank filled by transfers no more than 25 gallons at one time.)
Float Restrictor: ☐
Outside Alarm: ☐

Release Detection

Tank / Pipe

Manual Tank Gauging:	<input type="checkbox"/>	
Tank Tightness Testing:	<input type="checkbox"/>	
Inventory Control:	<input type="checkbox"/>	
Vapor Monitoring:	<input type="checkbox"/>	<input type="checkbox"/>
Groundwater Monitoring:	<input type="checkbox"/>	<input type="checkbox"/>
Automatic Tank Gauging:	<input type="checkbox"/>	<input type="checkbox"/>
Interstitial Monitoring:	<input type="checkbox"/>	<input type="checkbox"/>
SIR:	<input type="checkbox"/>	<input type="checkbox"/>
Auto Line Leak Detector:	<input type="checkbox"/>	<input type="checkbox"/>
Line Tightness Testing:	<input type="checkbox"/>	<input type="checkbox"/>
Sump Sensor:	<input type="checkbox"/>	<input type="checkbox"/>
Other Method:	<input type="checkbox"/>	<input type="checkbox"/>
Deferred:	<input type="checkbox"/>	<input type="checkbox"/>
Not Listed:	<input type="checkbox"/>	<input type="checkbox"/>
None:	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

ATG Mfg:		ATG Model:	
IM Mfg:		IM Model:	
SIR Vendor:		SIR Ver:	
Type of ALLD:		ALLD Mfg:	

Tank Information

Tank 1

Clerk: **CBoulind**
Modified: **10/30/2012 2:39:57 PM**

Substance Currently or Last Stored in Greatest Quantity by Volume

Substance: **Gasoline**
CERCLA No.:

Tank Closure or Change-In-Service

Closure Status: **Tank removed from ground**
Closure Observations:
Inert Fill:
Site Assessment Completed: ☐ Date Last Used:
Closed Date: **10/23/1990**
LUST Trust Fund Tank Removal: ☐ NFA Date:

Install / Repair / Service

Contractor	Work Performed	Notes	Date Work Performed
Sheldon Petroleum Service	Removal	10/23/90	10/23/1990



Facility Tank Information

Facility:	Shade Tree Inn	Facility ID No:	4260138
Street:	105 E. Main St.	Facility Description:	Gas Station
City ST Zip:	Glenwood, WA 98619	Operator:	
County:	Klickitat	Tribe:	Yakama
Phone:	(509) 364-3471	LUST Status:	NA
Latitude:	+46° 01' 18"	Longitude:	121° 17' 27"
Owner:	Shade Tree Enterprises, Inc.	Last Inspection Date:	Not Visited
Address:	105 E. Main St., P.O. Box 83	C&E Status:	No Visits
	Glenwood WA 98619	SOC Status:	In SOC
		SOC UST Status:	NA

Tank Comments

Source	Date	Comments
CBoulind	10/23/90	10/23/90
CBoulind	10/30/12	Actual date of install not recorded in available file material. NF form signed on 5/2/86 stated 11 - 15 years old at that time.



Facility Tank Information

Facility: **Shade Tree Inn** Facility ID No: **4260138**
Street: **105 E. Main St.** Facility Description: **Gas Station**
City ST Zip: **Glenwood, WA 98619** Operator:
County: **Klickitat** Tribe: **Yakama**
Phone: **(509) 364-3471** LUST Status: **NA**
Latitude: **+46° 01' 18"** Longitude: **121° 17' 27"** Last Inspection Date: **Not Visited**
Owner: **Shade Tree Enterprises, Inc.** C&E Status: **No Visits**
Address: **105 E. Main St., P.O. Box 83** SOC Status: **In SOC**
Glenwood WA 98619 SOC UST Status: **NA**

Tank Status Tank ID: **0002**
Alt Tank ID:
Compartment: ☐ Manifolder: ☐
Tank Status: **Permanently Out of Use**
Installation Date (Mo/Yr): **1/1/1971**
Est. Total Capacity (gallons): **3000**
Federally Regulated Tank: ☒

Tank Construction Material
Tank Material: **Asphalt Coated or Bare Steel**
Secondary Material:
Tank Manufacturer:
Tank Repaired: ☐ Used for Emergency Power Generation: ☐

Piping Construction Material
Piping Material: **Galvanized Steel**
Secondary Material:
Piping Manufacturer:
Type of Pipe: **Not Listed**
Piping Repaired: ☐ Metal in Contact with Ground: ☐

Corrosion Protection
☐ Yes ☒ No ☐ NA
FRP/ Flex Pipe: ☐
Impressed Current: ☐
Sacrificial Anodes: ☐
Interior Lining: ☐
Latest Upgrade Install Date:

Spill / Overfill Protection
Spill Protected: ☐ Exempt: ☐
Overfill Protected: ☐
(Check all that apply.) Ball Float: ☐ (Tank filled by transfers no more than 25 gallons at one time.)
Float Restrictor: ☐
Outside Alarm: ☐

Release Detection Tank / Pipe
Manual Tank Gauging: ☐
Tank Tightness Testing: ☐
Inventory Control: ☐
Vapor Monitoring: ☐
Groundwater Monitoring: ☐
Automatic Tank Gauging: ☐
Interstitial Monitoring: ☐
SIR: ☐
Auto Line Leak Detector: ☐
Line Tightness Testing: ☐
Sump Sensor: ☐
Other Method: ☐
Deferred: ☐
Not Listed: ☐
None: ☒ ☒

ATG Mfg: ATG Model:
IM Mfg: IM Model:
SIR Vendor: SIR Ver:
Type of ALLD: ALLD Mfg:

Substance Currently or Last Stored in Greatest Quantity by Volume
Substance: **Gasoline**
CERCLA No.:

Tank Closure or Change-In-Service
Closure Status: **Tank removed from ground**
Closure Observations:
Inert Fill:
Site Assessment Completed: ☐ Date Last Used:
Closed Date: **11/30/1988**
LUST Trust Fund Tank Removal: ☐ NFA Date:

Tank Information

Tank 2

Clerk: **CBoulind**
Modified: **10/30/2012 2:40:14 PM**



Facility Tank Information

Facility:	Shade Tree Inn	Facility ID No:	4260138
Street:	105 E. Main St.	Facility Description:	Gas Station
City ST Zip:	Glenwood, WA 98619	Operator:	
County:	Klickitat	Tribe:	Yakama
Phone:	(509) 364-3471	LUST Status:	NA
Latitude:	+46° 01' 18"	Longitude:	121° 17' 27"
Owner:	Shade Tree Enterprises, Inc.	Last Inspection Date:	Not Visited
Address:	105 E. Main St., P.O. Box 83	C&E Status:	No Visits
	Glenwood WA 98619	SOC Status:	In SOC
		SOC UST Status:	NA

Tank Comments

Source	Date	Comments
CBoulind	10/30/12	Actual date not recorded in file material forwarded from Ecology. Owner stated that it was prior to Dec. 1988. Actual date of install not recorded either. NF form signed on 5/2/86 stated 11 - 15 years old at that time.



Facility Tank Information

Facility: **Shade Tree Inn**Facility ID No: **4260138**Street: **105 E. Main St.**Facility Description: **Gas Station**City ST Zip: **Glenwood, WA 98619**

Operator:

County: **Klickitat**Tribe: **Yakama**Phone: **(509) 364-3471**LUST Status: **NA**Latitude: **+46 ° 01 ' 18 "** Longitude: **121 ° 17 ' 27 "**Last Inspection Date: **Not Visited**Owner: **Shade Tree Enterprises, Inc.**C&E Status: **No Visits**Address: **105 E. Main St., P.O. Box 83
Glenwood WA 98619**SOC Status: **In SOC**SOC UST Status: **NA**

Tank Status

Tank ID: **0003**

Alt Tank ID:

Compartment: ☐ Manifolder: ☐Tank Status: **Permanently Out of Use**Installation Date (Mo/Yr): **1/1/1966**Est. Total Capacity (gallons): **500**Federally Regulated Tank: ☒

Tank Construction Material

Tank Material: **Asphalt Coated or Bare Steel**

Secondary Material:

Tank Manufacturer:

Tank Repaired: ☐ Used for Emergency
Power Generation: ☐

Piping Construction Material

Piping Material: **Galvanized Steel**

Secondary Material:

Piping Manufacturer:

Type of Pipe: **Not Listed**Piping Repaired: ☐ Metal in Contact with Ground: ☐

Corrosion Protection

☐ Yes ☒ No ☐ NAFRP/ Flex Pipe: ☐Impressed Current: ☐Sacrificial Anodes: ☐Interior Lining: ☐

Latest Upgrade Install Date:

Spill / Overfill Protection

Spill Protected: ☐Exempt: ☐Overfill Protected: ☐(Tank filled by transfers
no more than 25 gallons
at one time.)(Check all
that apply.)Ball Float: ☐Float Restrictor: ☐Outside Alarm: ☐

Release Detection

Tank / Pipe

Manual Tank Gauging:	<input type="checkbox"/>	<input type="checkbox"/>
Tank Tightness Testing:	<input type="checkbox"/>	<input type="checkbox"/>
Inventory Control:	<input type="checkbox"/>	<input type="checkbox"/>
Vapor Monitoring:	<input type="checkbox"/>	<input type="checkbox"/>
Groundwater Monitoring:	<input type="checkbox"/>	<input type="checkbox"/>
Automatic Tank Gauging:	<input type="checkbox"/>	<input type="checkbox"/>
Interstitial Monitoring:	<input type="checkbox"/>	<input type="checkbox"/>
SIR:	<input type="checkbox"/>	<input type="checkbox"/>
Auto Line Leak Detector:	<input type="checkbox"/>	<input type="checkbox"/>
Line Tightness Testing:	<input type="checkbox"/>	<input type="checkbox"/>
Sump Sensor:	<input type="checkbox"/>	<input type="checkbox"/>
Other Method:	<input type="checkbox"/>	<input type="checkbox"/>
Deferred:	<input type="checkbox"/>	<input type="checkbox"/>
Not Listed:	<input type="checkbox"/>	<input type="checkbox"/>
None:	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

ATG Mfg: ATG Model: IM Mfg: IM Model: SIR Vendor: SIR Ver: Type of ALLD: ALLD Mfg:

Tank Information

Tank 3

Clerk: **CBoulind**Modified: **10/30/2012 2:40:25 PM**

Substance Currently or Last Stored in Greatest Quantity by Volume

Substance: **Diesel**CERCLA No.:

Tank Closure or Change-In-Service

Closure Status: **Tank removed from ground**Closure Observations: Inert Fill: Site Assessment
Completed: ☐Date Last Used: Closed Date: **11/30/1988**LUST Trust Fund
Tank Removal: ☐NFA Date:



Facility Tank Information

Facility:	Shade Tree Inn	Facility ID No:	4260138
Street:	105 E. Main St.	Facility Description:	Gas Station
City ST Zip:	Glenwood, WA 98619	Operator:	
County:	Klickitat	Tribe:	Yakama
Phone:	(509) 364-3471	LUST Status:	NA
Latitude:	+46° 01' 18"	Longitude:	121° 17' 27"
Owner:	Shade Tree Enterprises, Inc.	Last Inspection Date:	Not Visited
Address:	105 E. Main St., P.O. Box 83	C&E Status:	No Visits
	Glenwood WA 98619	SOC Status:	In SOC
		SOC UST Status:	NA

Tank Comments

Source	Date	Comments
CBoulind	10/30/12	Actual date of removal not recorded in file material forwarded from Ecology. Owner stated that it was prior to Dec. 1988. Actual date of install not recorded either. NF form signed on 5/2/86 stated 16 - 20 years old at that time.